Borges Construction Company

A limited liability Corporation

The following is a quote to retile the upstairs hall bathroom at your home:

	Hall Bathroom - Floor	<u>Materials</u>		Labor			
1	Remove tile base boards	\$	-	\$	25.00		
2	Remove toilet	\$	-	\$	25.00		Page 1
3	Remove existing tile and sub floor	\$	-	\$	180.00		
4	Scrape, clean and prep floor	\$	-	\$	15.00		
5	Install cement board (mortar & screw)	\$	54.00	\$	59.63		
6	Seal all seams	\$	2.00	\$	15.00		
7	Install tile (angled lay)	\$	10.00	\$	165.00		
8	Doors (3)	\$	-	\$	60.00		
9	Grout tile	\$	15.00	\$	35.00		
10	Install replacement baseboards	\$	15.00	\$	51.10		
11	Prime and paint base boards	\$	5.00	\$	20.00		
12	Reinstall toilet	\$	12.00	\$	35.00		
13	Sub total	\$	113.00	\$	685.73		
14	Sales tax	\$	9.83				
15	Total estimated cost	\$	122.83	\$	685.73	\$ 808.56	

^{**}All labor costs are firm. The above quote is for listed items only. Additional work including any unforeseeable complications and oversights will be invoice accordingly. Materials costs are subject to fluctuate**

Borges Construction Company

A limited liability Corporation

	Hall Bathroom - Shower	<u>Materials</u>		Labor			D 2
1	Remove existing tile and backer board	\$	-	\$	130.00		Page 2
2	Remove existing hardware	\$	-	\$	35.00		
3	Install replacement hardware	\$	30.00	\$	150.00		
4	Install cement board (glue & screw)	\$	91.00	\$	99.00		
5	Seal all seams	\$	7.50	\$	20.00		
6	Install & tile double recessed soap niche	\$	-	\$	176.53		
7	Install tile	\$	38.00	\$	665.50		
8	Grout tile	\$	25.00	\$	50.00		
9	Sub total	\$	191.50	\$	1,326.03		
10	Sales tax	\$	16.66				
11	Total estimated cost	\$	208.16	\$	1,326.03	\$ 1,534.19	

Notes: This estimate includes all materials associated with completing this work such as mortar, mastic, glue, ect.

This estimate does not include the cost of the product such as tile, tub hardware and double recessed soap niche.

^{**}All labor costs are firm. The above quote is for listed items only. Additional work including any unforeseeable complications and oversights will be invoice accordingly. Materials costs are subject to fluctuate**